

09-3.

**PROPERTY
OVERVIEW:**

**THE STENERSEN
MUSEUM**

M15

THE OLD STENERSEN COLLECTION (STENERSENMUSEET)

M15



Address: Munkedamsveien 15
Municipality: 0250
District: Sentrum

Qualitative criteria: Condition: A
Modularity: A

Cadastral Nr. GN 209 BN 209
Property Nr. 0301-209/209

Heritage status: None

Owner: Oslo Konserthus AS
Indirect owner: Municipality of Oslo
Ownership model: Exclusive ownership

Construction date: 1994
Architect: -
Developer: -

Original user: Stenersenmuseet
Current user: Oslo Konserthus AS

Surface area total:

Original use: Museum
Current use: Storage

Main usable area:
Additional area:
Public area:
Circulation area:


Closure date: 2015

Parcel area: 4 868 m²
Estimated value: -


Inventory : -
Source : OD2 PBE OSLO KOMMUNE
Pictured : -

FORMER PROGRAMME RATIO

M15



FORMER SURFACE AREA DISTRIBUTION



Inventory : -
Source : OD2 PBE OSLO KOMMUNE
Pictured : -

PROPERTY ROOM INDEX

M15

INDEX NR.	LEVEL	TYPE	HERITAGE STATUS	NET AREA	
M15-F0-R1	0	ST	UNLISTED	36.4	m ²
M15-F0-R2	0	ST	UNLISTED	26.3	m ²
M15-F0-R3	0	CI	UNLISTED	29.6	m ²
M15-F0-R4	0	N	UNLISTED	99.2	m ²
M15-F0-R5	0	ST	UNLISTED	85.7	m ²
M15-F0-R6	0	W	UNLISTED	79.1	m ²
M15-F0-R7	0	W	UNLISTED	36.4	m ²
M15-F0-R8	0	W	UNLISTED	112.9	m ²
F0-TOTAL	0	-	UNLISTED	43.8	m ²
M15-F1-R1	1	W	UNLISTED	19.0	m ²
M15-F1-R2	1	CI	UNLISTED	25.2	m ²
M15-F1-R3	1	W	UNLISTED	19.0	m ²
M15-F1-R4	1	W	UNLISTED	43.8	m ²
M15-F1-R5	1	ST	UNLISTED	85.2	m ²
M15-F1-R6	1	CI	UNLISTED	26.2	m ²
M15-F1-R7	1	N	UNLISTED	42.4	m ²
M15-F1-R8	1	N	UNLISTED	26.2	m ²
F1-TOTAL	1	-	UNLISTED	85.2	m ²
M15-F2-R1	2	W	UNLISTED	43.8	m ²
M15-F2-R2	2	N	UNLISTED	43.8	m ²
M15-F2-R3	2	N	UNLISTED	23.9	m ²
M15-F2-R4	2	N	UNLISTED	23.1	m ²
M15-F2-R5	2	N	UNLISTED	43.8	m ²
M15-F2-R6	2	N	UNLISTED	39.9	m ²
M15-F2-R7	2	ST	UNLISTED	62.2	m ²
M15-F2-R8	2	ST	UNLISTED	16.6	m ²
M15-F2-R9	2	W	UNLISTED	30.5	m ²
F2-TOTAL	2	-	UNLISTED	36.4	m ²

Inventory : B4-F-PROPERTY-OVERVIEW
Source : OD2 PBE OSLO KOMMUNE

PROPERTY ROOM INDEX

M15


ORIGINAL USE	CURRENT USE	CONSTRUCTION DATE	CONDITION
Storage	None	1994	Well Maintaned
Storage	None	1994	Well Maintaned
Staff entrance	None	1994	Well Maintaned
None	None	1994	Well Maintaned
Storage	None	1994	Well Maintaned
Documentation	None	1994	Well Maintaned
Conservation	None	1994	Well Maintaned
Administration	None	1994	Well Maintaned
Concierge			
Staff entrance	None	-	-
Concierge			
Back-of-house	None	1994	Well Maintaned
Storage	None	1994	Well Maintaned
Stairwell	None	1994	Well Maintaned
None	None	1994	Well Maintaned
None	None	1994	Well Maintaned
Server room	None	1994	Well Maintaned
None	None	1994	Well Maintaned
None	None	1994	Well Maintaned
None			
None	None	-	-
None			
Storage	None	1994	Well Maintaned
Storage	None	1994	Well Maintaned
Loading bay	None	1994	Well Maintaned
None	None	1994	Well Maintaned
Stairwell	None	1994	Well Maintaned
Storage	None	1994	Well Maintaned
Storage	None	1994	Well Maintaned
Conservation	None	1994	Well Maintaned
Documentation	None	1994	Well Maintaned
Stairwell			
Library	None	-	-

Inventory : B4-F-PROPERTY-OVERVIEW
Source : OD2 PBE OSLO KOMMUNE


ROOM INDEX NR. OVERVIEW

M15

BASEMENT



FIRST FLOOR




Inventory : 2412_DR_2D-M15
Source : OD2 PBE OSLO KOMMUNE
Drawings : Armand Zanota


ROOM INDEX NR. OVERVIEW

M15

SECOND FLOOR



ROOF



Inventory : 2412_DR_2D-M15
Source : OD2 PBE OSLO KOMMUNE
Drawings : Armand Zanota